

Fall 1976

Monitoring - Pesticides Disposal Sites

Lovelock - Soil (Pershing County)

50' North - None
50' East - None
50' South - None
50' East - None

Lovelock - Vegetation

50' North - .002 DDE; .003 H.E.
50' East - None
50' South - .002 DDE; .002 H.E.
50' West - .002 H.E.

Lovelock - Water

(1) Well 1 1/2 miles S.W. - None
(2) Well 2 Miles S.W. - None

Middle Reese - Soil (Lander County)

50' North - None
50' East - None
50' South - None
50' West - None

Middle Reese - Vegetation

50' North - None
50' East - None
50' South - None
50' West - None

Middle Reese - Water

(1) Powers Domestic Well - None

Orovada - Soil (Humboldt County)

50' North - None
50' East - None
50' South - .003 Aldrin
50' West - .001 Aldrin

Orovada - Vegetation

50' North - .003 DDT
50' East - .009 DDT
50' South - None
50' West - None

Orovada - Water

(1) Spring 1 3/4 miles S.W. - None
(2) Well 2 1/2 miles S.W. - None

Monitoring Pesticide Disposal Sites (Cont'd)

Fallon - Soil (Churchill County)

50' North - None
50' East - None
50' South - None
50' West - None

Fallon - Vegetation

50' North - None
50' East - None
50' South - None
50' West - None

Fallon - Water

(1) Well 1 Mile East - None

*H.E. = Heptachlor Epoxide

**Air not monitored at any site

***Samples taken 10-6-76 and 10-18-76